



Defect Listing

Pipe Segment Refere... E-16_E-15	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E-16	Total Length 120.3	Year Laid	Shape Circular		Location Details Side of road	
DS Manhole E-15	Length surveyed 120.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	


SPR 5	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI 5	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey		
QSR 5100	QMR N/A					
OPR 5	Surveyed By Barry Rogers	Direction Downstream	Date 20150605		Media label	
OPRI 5	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:23		Weather Dry	
Date Cleaned 20150605			End Time 14:32		Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	☐			
Remarks: E-16									
0.0 ft.	Water Level				5	☐			
7.9 ft.	Hole		6	2	0	☐	12	12	5
118.6 ft.	Water Level				5	☐			
120.3 ft.	Access Point Manhole				0	☐			
Remarks: E-15									




Image Report 4/Page


Pipe Segment Refere... E-16_E-15	City Oliver Springs	Street Sleepy Hollow	Material PolyVinyl Chloride		Location C... Yard	Sewer Use Sanitary
Upstream MH E-16	Total Length 120.3	Year Laid	Shape Circular		Location Details Side of road	
DS Manhole E-15	Length surveyed 120.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E-16



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 7.9 ft. Grade: 5
Condition: Hole
Remarks: N/A




Distance: 118.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E-16_E-15	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E-16	120.3		Circular	Side of road	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E-15	120.3		8	8	13



Distance: 120.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: E-15



PACP Conditions

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
E-16_E-15	Oliver Springs	Sleepy Hollow	PolyVinyl Chloride	Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
E-16	120.3		Circular	Side of road	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
E-15	120.3		8	8	13
SPR	5	MPR	N/A	PO Number	
SPRI	5	MPRI	N/A	Customer	
QSR	5100	QMR	N/A	GRW	
OPR	5	Direction	Date	Purpose	
OPRI	5	Downstream	20150605	Pre-Rehabilitation Survey	
	Surveyed By	Direction	Date	Media label	
	Barry_Rogers	Downstream	20150605	Media label	
	Certificate Number	Pre-Cleaning	Time	Weather	
	U-1012-16405	Jetting	14:23	Dry	
	Date Cleaned	End Time	Additional Info		
	20150605	14:32			

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects CodeIDLength			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	1	5	5	0	0	5	1	5
Subtotals			1			Subtotals	0		Subtotals	1	
SUMMARY			Pipe Rating Structural Index Str. Quick Rating	5 5.0 5100		Pipe Rating O&M Index O&M Quick Rating	0 0 0000		Overall Pipe Rating Overall Index Ovrl. Quick Rating	5 5.0 5100	