



Defect Listing

Pipe Segment Refere... A35-4_A35-3	City Oliver Springs	Street Hen Valley	Material PolyVinyl Chloride	Location C... Light High...	Sewer Use Sanitary
Upstream MH A35-4	Total Length 230.6	Year Laid	Shape Circular	Location Details Middle of the road	
DS Manhole A35-3	Length surveyed 230.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Dustin	Direction Downstream	Date 20150807	Media label	
OPRI N/A	Certificate Number U-214-06020262	Pre-Cleaning Jetting	Time 07:18	Weather Dry	
Date Cleaned 20150807			End Time 07:35	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	☐			
Remarks: A35-4									
0.0 ft.	Water Level				5	☐			
228.7 ft.	Tap Factory Made		8		0	☒	9		
229.8 ft.	Water Level				5	☐			
230.6 ft.	Access Point Manhole				0	☐			
Remarks: A35-3									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A35-4_A35-3	Oliver Springs	Hen Valley	PolyVinyl Chloride	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A35-4	230.6		Circular	Middle of the road	
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A35-3	230.6		8	8	13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A35-4



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 228.7 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 229.8 ft. Grade: 0
Condition: Water Level
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere... A35-4_A35-3	City Oliver Springs	Street Hen Valley	Material PolyVinyl Chloride		Location C... Light High...	Sewer Use Sanitary
Upstream MH A35-4	Total Length 230.6	Year Laid	Shape Circular		Location Details Middle of the road	
DS Manhole A35-3	Length surveyed 230.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13	



Distance: 230.6 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A35-3



PACP Conditions

Pipe Segment Refere... A35-4_A35-3	City Oliver Springs	Street Hen Valley	Material PolyVinyl Chloride		Location C... Light High...	Sewer Use Sanitary
Upstream MH A35-4	Total Length 230.6	Year Laid	Shape Circular		Location Details Middle of the road	
DS Manhole A35-3	Length surveyed 230.6	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey		
QSR N/A	QMR N/A					
OPR N/A	Surveyed By Dustin	Direction Downstream	Date 20150807		Media label	
OPRI N/A	Certificate Number U-214-06020262	Pre-Cleaning Jetting	Time 07:18		Weather Dry	
Date Cleaned 20150807			End Time 07:35		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings											
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating									
Normal Defects																				
Continuous Defects <table><tr><th>Code</th><th>ID</th><th>Length</th></tr><tr><td></td><td></td><td></td></tr><tr><td colspan="3"></td></tr></table>			Code	ID	Length							1	0	0	1	0	0	1	0	0
			Code	ID	Length															
			2	0	0	2	0	0	2	0	0	0								
			3	0	0	3	0	0	3	0	0	0								
4	0	0	4	0	0	4	0	0	0											
			5	0	0	5	0	0	5	0	0									
Subtotals			0			Subtotals	0		Subtotals	0										
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0										
			Structural Index	0		O&M Index	0		Overall Index	0										
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000										